

Firmware: V2.12

Hardware: B1

Date: 2020/11/19

Function modify:

1. Add WPA2 PSK-AES.
2. Change restore default WIFI default security to WPA2PSK-AES.
3. After setup wizard, WIFI security change to WPA2PSK-AES.
4. Add None security item in wireless setting page.

Note:

None

Known Issue:

None

=====

Firmware: V2.11

Hardware: B1

Date: 2020/08/01

Function modify:

1. Add WPA2 only
2. Optimize WPS

Note:

None

Known Issue:

None

=====

Firmware: V2.10

Hardware: B1

Date: 2019/12/23

Function modify:

1. Add IEEE802.11k/v/r

Note:

None

Known Issue:

None

=====

Firmware: V2.03

Hardware: B1

Date: 2019/11/08

Function modify:

1. Stricter device password(admin password) requirement in GUI.
2. Optimize FOTA query behavior.

Note:

None

Known Issue:

None

=====

Firmware: V2.02

Hardware: B1

Date: 2019/8/12

Function modify:

1. Upgrade WiFi Mesh Porting package to v1.05.07 which shorten provision time
2. Fix DAP can't sync FOTA setting after Mesh provision via Dlink Wifi APP
3. Fix 5G SSID can't be synced after Mesh provision
4. Fix Model Name can't be shown in Mesh topology issue

Note:

None

Known Issue:

None

=====

Firmware: V2.01

Hardware: B1

Date: 2019/1/25

Function modify:

1. HNAF command GetDeviceSettings add DeviceMACAddress.
2. Fix 0059778: FOTA upgrade firmware test - from iOS and Android APP Setup, The enforce messages did not pop up when user setup from iOS and AOS.

Note:

1. PSD-001-01009_D-Link Wi-Fi frequency table_20181102.pdf.

Known Issue:

1. Win 7 could not prompt remaindering user to press button when user click SSID from built-in ACM.
(MTK WIFI Driver IOT issue)

=====

Firmware: V2.00

Hardware: B1

Date: 2018/11/6

Function modify:

1. Fix FOTA FW upgrade sometimes fail.
2. Fix APP issue: HNAF SetFactoryDefault can't response before DUT reboot..

Note: 1st release for MP