

## DWR-920 LTE Mobile Router Release Notes

### CONFIDENTIAL

<b>Issue Date:</b>	Jan. 26, 2021
<b>Rev Date:</b>	January 29, 2021
<b>Version:</b>	<b>01.07.WW</b>
<b>HW version</b>	A1
<b>Project Code:</b>	N/A
<b>Base Model:</b>	N/A

## Revision History

Rev.	Comments	Date	Author
01.02.WW	Second Release	2019/8/24	Chris
01.03.WW	Third Release	2019/10/24	Chris
01.04.WW	Forth Release	2020/2/25	Chris
01.05.WW	Fifth release	2020/4/28	Chris
01.07.WW	Sixth Release	2021/1/26	Chris

### About this release (01.02.WW)

#### Release 01.02.WW the following update:

1. Fix the issue: DUT cannot get wan ip after change hostname.
2. Fix the issue: PC can access to Internet, but the led of WAN always show red after config the connection type to DHCP
3. Fix the issue: In WAN mode, internet LED shouldn't be red and solid.
4. Fix the issue: Won't load wan type setting.
5. Fix the issue: DUT image FW can be got files and folders after using "binwalk -Me" command to extract file
6. Fix the issue: DUT wan won't disconnect after on-demand set time.

### About this release (01.03.WW)

#### Release 01.03.WW the following update:

1. Fix the issue: The bridge mac will change when device reboot or reset.

### About this release (01.04.WW)

#### Release 01.04.WW the following update:

1. Fix the issue: Upgrade button sentence not getting finished.( DBG19120474)
2. Fix the issue: No login password mask after set by wizard.( DBG19120473)
3. Fix the issue: Spec. defined WLAN 2.4G LED dark according to no any RJ45 cable connected, test failed and WLAN 2.4G LED still light.( DBG19120467)
4. Fix the issue: does not define when LTE connection is disconnected.( DBG19120466)
5. Fix the issue: defined Internet LED dark according to WLAN radio is disabled, test failed and LED still light.( DBG19120465)
6. Fix the issue: does not define Signal LED status when No SIM card insert.( DBG19120464)
7. Fix the issue: SSL/TLS scan fail( DBG19120447)
8. add back PPPoE function except on demand

### About this release (01.05.WW)

1. fix the issue: can't send sms
2. upgrade the version number to 01.05.WW

### About this release (01.06.WW)

1. Client User enlarge from 10 to 32
2. upgrade the version number to 01.06.WW

**About this release (01.07.WW)**

**Release 01.07.WW the following update:**

- 1.DHCP LAN IP Range is 192.168.0.20 ~ 192.168.0.51by default
- 2.Update APN list to 2020 Q3 version
- 3.Fixed the issues in the PS-409-D 安全需求追溯表\_092019 (DWR-920 v01.05.WW)