![D-Link logo — BUILDING NETWORKS FOR PEOPLE]

DIR-X1860 A1 Firmware Release Notes

Firmware: 1.03B07

Hardware: A1

Date: 2020/9/29

Note:

N/A

Problems Resolved:

1. Fixed the client name cannot support space character issue.
2. Fixed HNAP tool issue.
3. Fixed Mydlink binding issues.
4. Fixed Intel AX200 2.4G IOT issue.

Enhancements:

1. Enhanced stability, performance and user experience.
2. Added EU VLAN in EU country code
3. Added DFS function in TH/SG/MY country code

Known Issues:

N/A