E15 Firmware Release Notes

Firmware: v1.05

Hardware: A1

Date: May 4th, 2022

==

Wi-Fi Country code support:

NA, US, TW, SG, SG1, AU, BR, LA, EU, IT, TH, ID, IN, CA, KR, RU, JP, BD, MA

DFS band support:

EU, IN, KR, TH, MA, JP

==

Problems Resolved:

- Fix connected extender randomly showed on client list.
- Fix Multicast streaming issue.
- Fix extender still provides Wi-Fi service even disable Wi-Fi on Main router.

Enhancements:

- Improve Mesh stability and connection.
- Improve Wi-Fi channel selection.
- Improve MU-MIMO.
- Improve WLAN/LAN device showed on client list with correct name/IP under each extender.
- Improve Ethernet Mesh/Legacy connecting issue. (Ai series)
- Improve LED behavior.
- Improve UI management.
- Support special character on device name.
- Support more Wi-Fi country code for specific region.

Known issues:

- Cannot add mesh node when Main router is under bridge mode.

==============================END==================================