



Firmware Version: V1.02.02
Prom Code Version:
Published Date: 2018/8/14

Content:

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: 2

Known Issues: 2

Related Documentation: 2

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.02.02	2018/08/14	DCS-8525LH	A1
V1.01.03	2018/05/29	DCS-8525LH	A1

Upgrading Instructions:

NA

New Features:

Fireware Version	New Features
V1.02.02	1. Update mydlink agent to v3.0.0-b75 2. Support mydlink Requirements for IoT Agent Version 1.0.6
V1.01.03	3. Update mydlink agent to v3.0.0-b64.1 4. Change Video spec , 1080P up to 1.5M bitrate

Problems Fixed:

Firmware Version	Problems Fixed
V1.02.02	1. Change IR cut minimum illumination. 2. Fix when sensitivity setup to 0%, it still can trigger motion detection.
V1.01.03	1. Reduce the echo noise on the device 2. Change PWR LED green on when LINK LED turn to green 3. Fix talk delay issue 4. Reduce video pixelization issue during PT moving

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A