



Software Version: V1.01.00B4
Camera Version: 1.01.20715
Agent Version: V3.0.0-b90
Published Date: 2018/11/19

Content:

| | |
|------------------------|---|
| Revision History: | 2 |
| New Features: | 2 |
| Enhancements: | 2 |
| Problems Fixed: | 2 |
| Known Issues: | 3 |
| Related Documentation: | 3 |

Revision History:

| Software Version | Date | Model | Hardware Version |
|------------------|------------|------------|------------------|
| V1.00.17B5 | 2018/07/20 | DCS-2802KT | A1 |
| V1.01.00B4 | 2018/10/25 | DCS-2802KT | A1 |

New Features:

| Software Version | New Features |
|------------------|--|
| V1.00.17B5 | 1. Initial Release |
| V1.01.00B4 | 1. HUB will report the MAC address of both Cameras 2. Privacy mode turns PIR detection completely off |

Enhancements:

| Firmware Version | Problems Fixed |
|------------------|----------------|
| | |

Problems Fixed:

| Software Version | Problems Fixed |
|------------------|---|
| V1.01.00B4 | 1. Fine-tuned day-night switch threshold value. 2. Fixed micro-SD card mounting and recognition issues. 3. Enhanced hub stability 4. Fine-tuned 3A learning 5. Fixed bug which caused CAM to report max 99% battery. 6. Corrected permission rights of Hub mydlink folder 7. Added self-diagnostic functions to hub. 8. Resolved the auto channel selection issue which impacted the streaming quality. 9. Improved the accuracy of battery and wireless signal strength readings 10. Reduced Sensitivity default to 30% 11. Improved USB Hard-drive compatibility 12. Modified DCS-H100 FLASH partition access permissions to meet D-Link requirements. |

Known Issues:

| Firmware Version | Known Issues |
|------------------|--------------|
| | |

Related Documentation:

N/A