



Software Version: 1.03.01
Agent Version: V3.6.10-b02
Published Date: 2021/02/24

Content:

Revision History 2

System Requirements (Minimum HW Requirements) 2

New Features 2

Enhancements 2

Problems Fixed..... 4

Known Issues 4

Related Documentation 4

Revision History

Software Version	Agent Version	Date	Model	Hardware Version
1.00.38	3.6.1-b01	2020/06/01	DCS-8635LH	A1
1.01.05	3.6.5-b01	2020/07/16	DCS-8635LH	A1
1.02.04	3.6.7-b06	2021/09/14	DCS-8635LH	A1
1.03.01	3.6.10-b02	2022/02/24	DCS-8635LH	A1

System Requirements (Minimum HW Requirements)

System Minimum Requirements	
System Requirements	mydlink APP for iPhone, iPad, Android phone and tablet.
Network Requirements	At least 1.5Mbps upload bandwidth per camera.
App Requirements	Compatible with iPhone and iPad using iOS 11 or higher Compatible with Android smartphones and tablets using Android 5.0 or higher

New Features

Software Version	New Features
1.00.38	NA
1.01.05	<ol style="list-style-type: none"> 1. Supports Notification when NPU is Fail 2. Support ONVIF Profile T
1.02.04	NA
1.03.01	NA

Enhancements

Firmware Version	Problems Fixed
1.00.38	NA
1.01.05	<ol style="list-style-type: none"> 1. Update the Vehicle detection algorithm.

	<ol style="list-style-type: none"> 2. Update the Glass breaking algorithm. 3. Update auto white balance algorithm. 4. Enhance home position will have gap after auto-tracking. 5. Support G.711 / AAC (Default AAC) audio codec via ONVIF protocol
1.02.04	<ol style="list-style-type: none"> 1. Support Synology ONVIF Profile T (synology Surveillance Station 8.2.10 Device Pack 5.8.4) 2. Run “check around” will filter motion detection. 3. Enhancement record file the audio and video sync. 4. Enhancement security issue “UDP flood”.
1.03.01	<ol style="list-style-type: none"> 1. Upgrade Openssl to 1.1.1l

Problems Fixed

Software Version	Problems Fixed
1.00.38	NA
1.01.05	1. Fixing WiFi FragAttack vulnerabilities. 2. Fixing password change fail issue via ONVIF.
1.02.04	1. Fixing sometimes the D-Link logo display location will incorrect. 2. Fixing UUID response issue via ONVIF. 3. Fixing snapshot fail issue via ONVIF media2. 4. Fixing FW upgrade fail issue
1.03.01	1. Fixed the image have horizontal stripes when the object near camera lens. 2. Fixed the Wi-Fi connection fail after change security mode from to WPA2. 3. Fixed video recording will stop sometime.

Known Issues

Firmware Version	Known Issues

Related Documentation

N/A