

## **G415 Firmware Release Notes**

**Firmware: v1.08 (1<sup>st</sup> released version)**

**Hardware: A1**

**Date: Mar. 22<sup>nd</sup>, 2023**

### **Problems Resolved:**

- Support “auto upgrade LTE module FW” feature to fix 4G internet disconnect/reconnect issue in certain ISP.
- Implement the latest Wi-Fi patch to fix “call trace & reboot” issue with M15 found in mesh endurance test.
- Fix the issue of “when SMS contain emoji characters, user will jump out of SMS inbox and can’t access inbox to check SMS”
- 2 HOP wireless extender does not upgrade to FOTA version.

### **Enhancements:**

- Implement the latest APN list (2023 Q1 version).
- Remove the redundant check box icon on SMS inbox to prevent confusion.

### **Known issues:**

- When user use Eagle pro AI APP (AOS version) and set device at router mode with PPPoE, after setting Wi-Fi SSID, the Wi-Fi will disconnect and need user to manually connect Wi-Fi again to finish setup wizard process.

=====END=====