

DAP-1610 Firmware Release Notes

Firmware: v2.02

Hardware: B1

Date: March 8th, 2023

Problems Resolved:

- Fix potential security issue.
- Fix QR code scanning issue on iOS device.
- Fix QR code button fails on specific mobiles (Xiaomi, Smartisan).

Enhancements:

- Improve web management page (Wi-Fi status, Typo).
- Improve connecting process through WPS button.

Known Issues:

- None

=====END=====